

CRP5 Release Notes

Firmware Version 1.2

Change Control

Enhancements/Improvements:

- Menu protection for differential pressure-, Humidity-, and temperature settings must be protected against for external operation.
- If the keylock is activated, the icons on the left side aren't visible.
- The menu is blocked during a firmware update.

Bugs fixed:

- Adjusting over the keyboard
- For differential pressure adjustment, the filter is turned off.
- Calibration over the front nozzles.
- Improvement analog input mA, please see the Manual E-M-CRP5-V1_1_EN